

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



1. Well sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



3. Well location overview.



4. Shared remote meter shed. Lease sign at shed is incorrect and reflects Salvador 6-5 instead of Salvador 2-5.

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612

Station ID#		Lease Name		Differential	
7115217		SALVADOR 6-5		Inches in H ₂ O	
Cal SP Span		Federal or State ID#		Static	
0-400#		125-06612		PSIG	
Cal DP span		Section		Temperature	
0-250"		5		In Fahrenheit	
SP Range		Township		Tap Location	
Temp Range		4N		Downstream	
D-800#		Range			
-40° to 160°		46W			
DP Range		Contract Hour			
0-250"		8			
Tech		Atm Pressure		Pressure Base	
		12.7		14.73	
Cal Date		Orifice Bore			
CAL 1/28/20					
.375 NB					
PLT CHG 9/28/20					
.375 TO .25 NB					
CAL 3-8-21					
NB .25					
BJ 11/28/2022 .250					
BJ 03/18/2024 .250					

5. Calibration log inside remote meter shed reflects data for well API #125-06612. Lease name is incorrect.



6. Sign posted on remote meter shed.

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



7. Flowline mounted separator cabinet at remote gathering location.



8. Vertical separator inside cabinet.

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



9. Gas meter inside shared remote meter shed.



10. View of produced water pit at remote gathering location.

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



11. Pit and shared gathering location overview.



12. Remote gathering location overview.