

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location #323790 Facility #456910

Date: 12/5/2024



Photo # 0415 Domestic tap



Photo # 0425 PRV vent line does not comply with CECMC pressure safety device rules