

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404022041

Date Received:

12/10/2024

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers
Address: <u>1099 18TH STREET SUITE 1500</u>		Phone: <u>(303) 860-5800</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Karen Olson</u>		Mobile: <u>()</u>
		Email: <u>Karen.olson@chevron.com</u>

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORTInitial Spill/Release Report Doc# 404022041Initial Report Date: 12/10/2024 Date of Discovery: 12/08/2024 Spill Type: Recent Spill**Spill/Release Point Location:**QTRQTR NESE SEC 30 TWP 6N RNG 67W MERIDIAN 6Latitude: 40.454987 Longitude: -104.927483Municipality (if within municipal boundaries): Windsor County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☐ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:Facility Type: TANK BATTERY☒ Facility/Location ID No 451100Spill/Release Point Name: Raindance FD☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=5 and <100Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: 30s, night

Surface Owner: FEE Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A reportable release occurred on 12/8/24 at the Raindance FD tank battery. Approximately 19.8 BBL of produced water released from a corroded load out line. The release was fully contained within poly lined containment with steel berm walls. Hydrovac operations are complete and all standing fluids have been removed. An investigation into the integrity of the liner was conducted on 12/9/2024 after all produced water had been removed from containment. Note that no pea gravel had been in containment. The liner was determined to be fully intact with no rips, tears or holes.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
12/9/2024	Municipality of Windsor	Scott Ballstadt	--	Email
12/9/2024	Surface Owner	N/A	--	Verbal Notice
12/9/2024	Weld County	David Burns	--	Email
12/9/2024	Weld County	Brett Cavanagh	--	Email
12/9/2024	ECMC	Rick Allison	--	Email

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____
Residence or Occupied Structure: _____ Livestock: _____
Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
Enter the Document Number of the Initial Accident Report, Form 22 _____
Was there damage during excavation? _____
Was CO 811 notified prior to excavation? _____

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____

No	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply: <input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water
No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight's from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 12/10/2024		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	20	20	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>50</u>		Width of Impact (feet): <u>50</u>	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
Released fluids have been fully contained within lined containment bordered with steel wall berms. An investigation into the integrity of the liner was conducted on 12/9/2024 after all produced water had been removed from containment. Note that no pea gravel had been in containment. The liner was determined to be fully intact with no holes, rips or tears. Therefore, no soil samples shall be collected as the soil was never impacted. See attached photolog.			
Soil/Geology Description:			
Poly liner.			
Depth to Groundwater (feet BGS) <u>27</u>		Number Water Wells within 1/2 mile radius: <u>3</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1718</u> None <input type="checkbox"/>	Surface Water <u>3055</u> None <input type="checkbox"/>	
	Wetlands <u>3757</u> None <input type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>727</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

Date Run: 12/10/2024 Doc [#404022041]

No additional spill details.

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 12/10/2024

Root Cause of Spill/Release Corrosion

Other (specify)

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Load out line from tank battery.

Describe Incident & Root Cause (include specific equipment and point of failure)

On 12/8/2024, a Raindance tank battery load out line corroded between the tanks and pump.

Describe measures taken to prevent the problem(s) from reoccurring:

In order to prevent this issue from reoccurring, PDC has replaced the entire load out line with steel piping. Additionally, PDC uses a chemical corrosion inhibitor in all Raindance wells to mitigate corrosion within lines as produced water is highly corrosive. Samples of the chemical can be collected and analyzed to determine the effectiveness of the chemical. Based on the results of the samples the chemical corrosion inhibitor solution can be adjusted to meet the needs of the specific infrastructure that it is in contact with. Further, PDC conducts annual integrity tests on all facility lines.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation)

☐ Offsite Disposal

☐ Onsite Treatment

☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached, check all that apply)

☒ Horizontal and Vertical extents of impacts have been delineated.

☒ Documentation of compliance with Table 915-1 is attached.

☒ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: _____

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

PDC respectfully requests closure of this Spill/Release based on the complete remediation of this site as demonstrated in the Spill/Release Detail Report section of this document.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Michelle Bartoszek

Title: HSE Advisor Date: 12/10/2024 Email: michelle.bartoszek@chevron.com

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
404022391	TOPOGRAPHIC MAP
404022432	PHOTO DOCUMENTATION

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)