


Photographic Log - Before Photos
Raindance FD Tank Battery
December 8, 2024



Equipment ID:			Equipment Type:		
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Release point on load out line.			Notes/Conditions: Containment full of produced water, before clean up.		

Photographic Log - Before Photos
Raindance FD Tank Battery
December 8, 2024



Equipment ID:			Equipment Type:		
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Containment full of produced water, before clean up.			Notes/Conditions: Containment full of produced water, before clean up.		

Photographic Log - Before Photos
Raindance FD Tank Battery
December 8, 2024



Equipment ID:			Equipment Type:		
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Containment full of produced water, before clean up.			Notes/Conditions: Release point on load out line.		

Photographic Log - After Photos
Raindance FD Tank Battery
December 10, 2024



Equipment ID:			Equipment Type:		
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Containment and intact liner post hydrovac operations looking east.			Notes/Conditions: Containment and intact liner post hydrovac operations looking north.		

Photographic Log - After Photos
Raindance FD Tank Battery
December 10, 2024



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Containment and intact liner post hydrovac operations looking north.			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Containment and intact liner post hydrovac operations looking south.			

Photographic Log - After Photos
Raindance FD Tank Battery
December 10, 2024



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Containment and intact liner post hydrovac operations looking inside containment.			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Containment and intact liner post hydrovac operations looking inside containment.			

Photographic Log - After Photos
Raindance FD Tank Battery
December 10, 2024



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Containment and intact liner post hydrovac operations looking inside containment.			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Containment and intact liner post hydrovac operations looking west inside containment.			

Photographic Log - After Photos
Raindance FD Tank Battery
December 10, 2024



Equipment ID:			Equipment Type:		
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Containment and intact liner seal against steel berm wall post hydrovac operations.			Notes/Conditions: Containment and intact liner seal against steel berm wall post hydrovac operations.		