

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404022521

Date Received:
12/10/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>ERIN JOSEPH</u>	<u>970-515-1169</u>	<u>ECMCInspections@Oxy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714300150
Inspection Date: 11/14/2024 FIR Submit Date: 11/19/2024 FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____
Qtrqtr: NENE Sec: 20 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.130335 Longitude: -104.794670

FACILITY - API Number: 05-123-00 Facility ID: 488435

Facility Name: Schmidt Paul B GU 1 Facility Number: _____
Qtrqtr: NENE Sec: 20 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.130335 Longitude: -104.794670

CORRECTIVE ACTIONS:

1 CA# 200545

Corrective Action: Operator shall provide an updated Form 27 for Remediation #36652 with a workplan and timeline for remediation of Spill ID 488435. Date: 12/03/2024

Response: CA COMPLETED Date of Completion: 12/03/2024

Operator Comment: An updated Form 27 for Remediation Project #36652 was submitted on 11/19/2024 under document number 403964304. Excavation activities are still ongoing to remediate impacts.

ECMC Decision: _____

ECMC
Representative:

2 CA# 200546

Corrective Action: If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/03/2024

Operator Comment: The stockpile was removed on 11/21/24 (see attached photos). Soil samples were collected from underneath the observed soil stockpile area on 11/26/24.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: SR REGULATORY ADVISOR

Date: 12/10/2024 2:04:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404022521	FIR RESOLUTION SUBMITTED
404022533	LOCATION PHOTOS

Total Attach: 2 Files