

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404022653

Date Received:
12/10/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

| | |
|---|---------------------------------|
| ECMC Operator Number: 47120 | Contact Name and Telephone: |
| Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP | Name: _____ |
| Address: P O BOX 173779 | Phone: () _____ Fax: () _____ |
| City: DENVER State: CO Zip: 80217-3779 | Email: _____ |

Additional Operator Contact:

| | | |
|--------------|--------------|-------------------------|
| Contact Name | Phone | Email |
| ERIN JOSEPH | 970-515-1169 | ECMCInspections@Oxy.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 714300148
Inspection Date: 11/14/2024 FIR Submit Date: 11/19/2024 FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____
Qtrqtr: NESE Sec: 21 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.122184 Longitude: -104.774717

FACILITY - API Number: 05-123- -00 Facility ID: 488471

Facility Name: Sugihara 43-21 Wellhead Number: _____
Qtrqtr: NESE Sec: 21 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.122184 Longitude: -104.774717

CORRECTIVE ACTIONS:

1 CA# 200541

Corrective Action: If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure.

Date: _____

Response: CA COMPLETED Date of Completion: 12/03/2024

Operator Comment: Soil stockpiles were removed from the Sugihara 43-21 Wellhead excavation area. Soil samples were collected from underneath the observed soil stockpile area on 12/3/24.

ECMC Decision: _____

| | |
|-------------------------|--|
| ECMC Representative: | |
|-------------------------|--|

| | |
|---|-----------------------------|
| OPERATOR COMMENT AND SUBMITTAL | |
| Comment: | |
| I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete. | |
| Print Name: ERIN JOSEPH | Signed: _____ |
| Title: SR REGULATORY ADVISOR | Date: 12/10/2024 2:42:20 PM |

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------------|
| 404022653 | FIR RESOLUTION SUBMITTED |
| 404022657 | LOCATION PHOTO |

Total Attach: 2 Files