

Inspection Photos

API: 071-09062

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road.



Inspection Photos



Photo 2. Facing toward the wellsite. There is a dripping water leak at the wellhead that needs to be controlled.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing toward the wellsite. There is a dripping water leak at the wellhead that needs to be controlled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09062 | Date: 12/9/2024