

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912



Photo 1 Location

Photo 2 Spotty Stained soil west of the WH.

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912



Photo 3 Stained soil around the WH.



Photo 4 WH sign.

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912



Photo 5 Pump jack.



Photo 6 Stained soil by the gas engine pressure tank.