

Inspection Photos
Location Name: Sydney Strear Unit 1
Location ID: 317923



Photo 1 Location



Photo 2 Dead vegetation throughout the Wellsite.

Inspection Photos
Location Name: Sydney Strear Unit 1
Location ID: 317923



Photo 3 Stained soil & dead vegetation around the WH.



Photo 4 WH sign.

Inspection Photos
Location Name: Sydney Strear Unit 1
Location ID: 317923



Photo 5 Dead vegetation all around the ancillary equipment.



Photo 6 Dead vegetation all around the Wellsite.

Inspection Photos
Location Name: Sydney Strear Unit 1
Location ID: 317923



Photo 7 Dead vegetation all around the location.