

Inspection Photos

API: 071-06819

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road.



Inspection Photos



Photo 2. There is a stormwater diversion installed where run-off from the location was occurring. Road base material was hauled into this area for a slight water bar.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06819 | Date: 12/9/2024

Inspection Photos



Photo 3. Facing toward the wellsite.

