

# Inspection Photos

API: 071-07279

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-07279 | Date: 12/9/2024

## Inspection Photos



December 9, 2024  
+36.996878, -104.780517  
Las Animas County  
ECMC

**Photo 2.** Sign posted on meter run.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-07279 | Date: 12/9/2024

## Inspection Photos



**Photo 3.** Facing toward the south side of the location. Ubnused areas of the location are reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources