

Inspection Photos

ID: 453010

Operator: OGRIS OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main road to the compressor facility.



Inspection Photos



Photo 2. A sediment trap was installed to prevent erosion onto the road.

