

Inspection Photos

ID: 478058

Operator: OGRIS OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main road to the A.C. Tank Battery. A sediment ahs been installed along the road side. The rock barriers may be obscured during snow accumulation. Reflector markers may be more suited at this area.



Inspection Photos



Photo 2. Facing southwest toward the access road adjacent to the main road. Additional rock rip rap has been installed to armor the roadside where erosion was occurring.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 12/9/2024

Inspection Photos



Photo 3. Facing northwest toward the tank battery. There are still some stained soils that will require cleanup. O



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 12/9/2024

Inspection Photos



Photo 4. Facing toward the tank battery. The open top tank has been removed.

