

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055

Inspection Doc: 718100096

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



Photo 2: See comments under photo 1. Photos also show areas on the west end of the Location that or not necessary for production have not been reclaimed pursuant to 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 3: Photos top left/right from the 8/9/2024 inspection; photo right dated 12/10/2024. Photo shows marker remains missing. Photos examples showing missing markers identified on 8/9/2024 have not been installed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



Photo 4: Photos examples showing risers remaining on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055




Photo 5: Photo examples showing cellars at wells have not been properly covered.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources