

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335054

Inspection Doc: 718100098

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335054



Photo 1: Photos taken from the north and east ends of the working pad surface. Photos show areas where stormwater runoff was document discharging from the working pad surface, resulting in sediment transport/deposition and degradation to the interim areas of the Location. Unable to find evidence that work to install or repair BMPs to properly manage runoff has been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335054



Photo 2: Lines at tanks have been capped/plugged.