

Inspection Photos
Location Name: Charles C Bell Unit 1
Location ID: 317754



Energy & Carbon Management Commission
40.14004, -104.78515, 4850.5ft, 148°
12/11/2024 15:30:09



Energy & Carbon Management Commission
40.13994, -104.785, 4852.6ft, 184°
12/11/2024 15:28:40

Photo 1 Location

Photo 2 Wellhead.

Inspection Photos
Location Name: Charles C Bell Unit 1
Location ID: 317754



Photo 3 Wellhead.

Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Charles C Bell Unit 1
Location ID: 317754



Photo 5 Tank Battery.

Photo 6 Tank Battery sign.

Inspection Photos
Location Name: Charles C Bell Unit 1
Location ID: 317754



Photo 7 Flow line manifold.

Photo 8 Horizontal Heated Separator.

Inspection Photos
Location Name: Charles C Bell Unit 1
Location ID: 317754



Photo 9 Gas Meter Run.



Photo 10 trash.