

Cullen Chew

From: Patrick Lawler <plawler@quandaryconsultants.com>
Sent: Tuesday, December 10, 2024 12:53 PM
To: Cullen Chew
Subject: [EXTERNAL]Fw: KPK Flowline Release Notification - Mule Deer Severe Winter Range - Lost Creek State 1-32
Attachments: Fig1_Lost Creek State 1-32.pdf; Fig2_Lost Creek State 1-32.pdf; Lost Creek State 1-32 Flowline Spill.kmz

Please be cautious: KPK External Sender Notice: This email is from an external sender. Please take care when clicking links or opening attachments. When in doubt, contact your IT Department

Hi Cullen,
I believe this is the email you were referring to - it doesn't look like a response was received.
Please let me know if you need anything else.
Thanks,

Patrick Lawler
C: (720) 480.1035

From: Katherine Kahn <kkahn@quandaryconsultants.com>
Sent: Tuesday, December 10, 2024 12:50 PM
To: Patrick Lawler <plawler@quandaryconsultants.com>
Subject: Fw: KPK Flowline Release Notification - Mule Deer Severe Winter Range - Lost Creek State 1-32

Katherine Kahn, P.G. | Senior Hydrogeologist
C: 303.319.9604 | KKahn@QuandaryConsultants.com
4480 Garfield Street, Denver, CO 80216



Please note – I will be out of the office with limited email access from March 16-26, 2024.

From: Chris Cooper <Ccooper@quandaryconsultants.com>
Sent: Wednesday, December 13, 2023 6:39 PM
To: Marette - DNR, Brandon <brandon.marette@state.co.us>; Lexi Hamous-Miller - DNR <lexi.hamous-miller@state.co.us>
Cc: John Peterson <JPeterson@kpk.com>; Katherine Kahn <kkahn@quandaryconsultants.com>; Corinna Photos <cphotos@quandaryconsultants.com>
Subject: RE: KPK Flowline Release Notification - Mule Deer Severe Winter Range - Lost Creek State 1-32

Good evening Brandon/Lexi–

Brandon, thanks for taking time to speak with me this afternoon regarding this email. Our client, KP Kauffman Company (KPK), had a small flowline release at the Lost Creek State 1-32 site on Tuesday, December 12, 2023, at 9:00 a.m. It was estimated to be approximately 1 yard of oil and produced water released from the flowline at this

site which is located within Mule Deer Severe Winter Range (agriculture field). Please see the attached figures and kmz file which show the location of the release.

Per ECMC guidance for Rule 912.b.(1)A-K Reporting Spills and Releases, Section (10), the Operator is to provide verbal or written notification to CPW if the Spill or Release occurred within High Priority Habitat. The area had a plastic liner laid down immediately to prevent any further release and the contaminated soil is being excavated and removed from the site. The section of flowline which was compromised will also be repaired. There was no water bodies/WOTUS, wildlife, or livestock in the area or affected at the time of the release.

This release was reported to all other appropriate agencies and the surface owner per Rule 912.b.(1)A-K. Please let us know if anything further is needed for CPW notification at this time.

Thank you,

Chris Cooper | Sr. Project Manager, Natural Resources
C: 720.722.8607 | CCooper@QuandaryConsultants.com
4480 Garfield Street, Denver, CO 80216

