

Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325530

Inspection Document #: 714001574

La Plata County, CO

Township: SESW 10 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mayfield A1
Location ID: 325530



Photo 1. View of well taken from the southern edge facing center.



API #: 067-06559

12/11/24
51° NE



Inspection Photos
Location Name: Mayfield A1
Location ID: 325530



Inspection Photos
Location Name: Mayfield A1
Location ID: 325530



Photo 4. Gully erosion forming on the southern edge of the active pad.

Inspection Photos
Location Name: Mayfield A1
Location ID: 325530



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed predominantly of Big Sagebrush and Juniper.

API #: 067-06559