

# Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 307006

Inspection Document #: 714001575

La Plata County, CO

Township: SESW 10 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mayfield A3  
Location ID: 307006

12/11/24  
213° SW



Photo 1. View of well taken from the northern edge facing center.

Inspection Photos  
Location Name: Mayfield A3  
Location ID: 307006

12/11/24  
252° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area composed of Sand Dropseed, Smooth Brome and Rabbitbrush.

API #: 067-09471

Inspection Photos  
Location Name: Mayfield A3  
Location ID: 307006

12/11/24  
237° SW



**Photo 3.** Erosion starting to form at the access point, future maintenance is advised.

Inspection Photos  
Location Name: Mayfield A3  
Location ID: 307006

12/11/24  
176° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed predominantly of Big Sagebrush, Squirrel tail and Juniper.

API #: 067-09471