

Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333701

Inspection Document #: 714001576

La Plata County, CO

Township: SWNW 10 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
 Location Name: Mayfield A2, A4
 Location ID: 333701

12/11/24
 346° N



Photo 1. View of well pad taken from the northern edge facing center.

Inspection Photos
Location Name: Mayfield A2, A4
Location ID: 307006

12/11/24
314° NW



Photo 2. View of eastern interim reclamation area composed of Smooth Brome, Rabbitbrush and Western Wheatgrass.

Inspection Photos
Location Name: Mayfield A2, A4
Location ID: 307006

12/11/24
141° SE



Photo 3. Produced water tank label/placard deteriorating and no longer displaying capacity.

Inspection Photos
Location Name: Mayfield A2, A4
Location ID: 307006



Photo 4. Large patch of Musk Thistle observed along the access road. Evidence that Musk Thistle has gone to seed this season.

Inspection Photos
Location Name: Mayfield A2, A4
Location ID: 307006

12/11/24
46° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Western Wheatgrass, Juniper and Big Sagebrush.

API #: 067-8935, 09504