

Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333442

Inspection Document #: 714001577

La Plata County, CO

Township: NWNW 11 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: George 11-11 1, 3
Location ID: 333442



12/11/24
44° NE



12/11/24
351° N

Photo 1. View of well pad taken from the southern edge facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07686, 09137

12/11/24
43° NE



Photo 2. Erosion observed at the access point.

Inspection Photos
Location Name: George 11-11 1, 3
Location ID: 333442

12/11/24
330° NW



Inspection Photos
Location Name: George 11-11 1, 3
Location ID: 333442



Photo 4. Marked guyline anchors on the active pad.

Inspection Photos
Location Name: George 11-11 1, 3
Location ID: 333442



Photo 5. Impacted surface material observed at well head #1.



Inspection Photos
Location Name: George 11-11 1, 3
Location ID: 333442

12/11/24
0° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed of Crested Wheatgrass, Sagebrush and Juniper.

API #: 067-07686, 09137