

Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334213

Inspection Document #: 714001582

La Plata County, CO

Township: NWNW 7 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gary BeeBee B1, B3
Location ID: 334213



Photo 1. View of well head assembly and location/well signs.



Inspection Photos
Location Name: Gary BeeBee B1, B3
Location ID: 334213



Photo 2. Marked guyline anchors on location.



12/11/24
329° NW



12/11/24
289° W



Photo 4. Excavator stored on the western edge of the disturbance.



Inspection Photos
Location Name: Gary BeeBee B1, B3
Location ID: 334213

12/11/24
73° E

