

Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333449

Inspection Document #: 714001583

La Plata County, CO

Township: NESW 13 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neil 34-13 2, 4
Location ID: 333449



Photo 1. View of the wellhead assembly and location/well sign.

Inspection Photos
Location Name: Neil 34-13 2, 4
Location ID: 333449



Photo 2. Placards/Signs at separators are deteriorating, future maintenance is advised.

Inspection Photos
Location Name: Neil 34-13 2, 4
Location ID: 333449



Inspection Photos
Location Name: Neil 34-13 2, 4
Location ID: 333449



Photo 4. Russian thistle debris remain dominating the fill slope interim reclamation area and is interfering with establishment of perennial vegetation.

Inspection Photos
Location Name: Neil 34-13 2, 4
Location ID: 333449

12/11/24
359° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Rabbitbrush, Intermediate Wheatgrass and Mullein.

API #: 067-09054, 09100