

Inspection Photos
Location Name: Marie Gerhardt B 8
Location ID: 318384



Photo 1 Dead vegetation throughout location.



Photo 2 Dead vegetation throughout location.

Inspection Photos
Location Name: Marie Gerhardt B 8
Location ID: 318384



Energy & Carbon Management Commission
40.11789, -104.85289, 4868.9ft, 70°
12/12/2024 14:47:36



Energy & Carbon Management Commission
40.11794, -104.85285, 4860.9ft, 134°
12/12/2024 14:47:46

Photo 3 Wellhead sign.

Photo 4 Wellhead.

Inspection Photos
Location Name: Marie Gerhardt B 8
Location ID: 318384



Photo 5 Dead vegetation around the ancillary equipment.