

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 3469 From entrance to location



Photo # 3470 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 3471 Location



Photo # 3472 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 3473 Location



Photo # 3474 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 3475 Location




Photo # 3476 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Dec 12, 2024 at 11:59:29 AM  
CO

Photo # 3477 Location



Dec 12, 2024 at 11:49:51 AM  
CO

Photo # 3478 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



**Photo # 3479 Staining in secondary containment**



**Photo # 3480 Pig station & Summit Midstream meter house not listed in FORM 2A/not in compliance with CECMC rules**