

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 12/11/2024



Location Entrance – Photo #05250



Location – Photo #05253

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 12/11/2024



Location – Photo #05251



Location – Photo #05252



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 12/11/2024



Unprotected Soil Stockpile – Photo #05255



Unprotected Soil Stockpile – Photo #05256