

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location ID: 324116

Date: 12/11/2024



Location Entrance – Photo #05264



Location – Photo #05265

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location ID: 324116

Date: 12/11/2024



Location – Photo #05267




Location – Photo #05268

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT-67S96W/1NENW

Location ID: 324116

Date: 12/11/2024



Weathered and Illegible Wellhead Sign – Photo #05266