

# Inspection Photos

December 11th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334175

Inspection Document #: 714001584

La Plata County, CO

Township: N7E 18 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dollahan 18U-01 2, 4  
Location ID: 334175



**Photo 1.** View of well disturbance taken from the access point facing center.  
Note: large truck stored on location.

Inspection Photos  
Location Name: Dollahan 18U-01 2, 4  
Location ID: 334175



**Photo 2.** Bins and chemical tubs stored on location with impacted surface material.

12/11/24  
89° E



Inspection Photos  
Location Name: Dollahan 18U-01 2, 4  
Location ID: 334175



**Photo 4.** Formed gully erosion observed in the eastern portion of the pad.

Inspection Photos  
Location Name: Dollahan 18U-01 2, 4  
Location ID: 334175



**Photo 5.** View of unused oil and gas piping observed on location.