

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0441 Entrance to location



Photo # 0459 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0446 Location



Photo # 0452 Location



## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0458 Location



Photo # 0471 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0500 Location SE corner of location



Photo # 0501 SW corner of location



## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0506 NE corner of location



Photo # 0507 NW corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0479 Wildlife hazard




Photo # 0483 Wildlife hazard



## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024



Photo # 0485 Wildlife hazard



Photo # 0487 Wildlife hazard

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/2-31 Pad

Location ID: 312568

Date: 12/10/2024




Photo # 0496 Wildlife hazard




Photo # 0499 Wildlife hazard