

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 418828

Inspection Doc: 718100103

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 418828



Photo 1: Photos taken from the Location entrance, facing northeast and southeast. Stock Tank stored on the pad has been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 418828



Photo 2: Photo taken from the Location entrance. Signage remains posted with two Operators. Emergency contact number has also not been update; number posted is no longer in service.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 418828



December 10, 2024

Photo 3: Photos 3-5 taken from the working pad surface on the southeast end of the Location. Photos shows tracking/rutting/degradation has persisted on the pad.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 418828



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 418828



Photo 5: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources