

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 334708

Inspection Doc: 718100107

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 334708



Photo 1: Photos show Operator has placed netting at the methanol tank's secondary containment. BMP has not been maintained in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 334708



Photo 2: Unused equipment remaining on the west end of the Location.