



Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#1 this segment of
pipe is what failed

Dec 5, 2024 12:59:40 PM
40.10050778277218N 108.86222787201405W
8524 County Road 2
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Dec 5, 2024 1:00:43 PM
40.10048414580524N 108.8622269500047W
Unnamed Road
Rangely
Rio Blanco County
Colorado

Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#2 photo is looking
the direction that the spill
path took.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#3 photo is looking
the direction that the spill
path took.

Dec 5, 2024 1:01:01 PM
40.10049085132778N 108.86207029223442W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Dec 5, 2024 1:02:27 PM
40.100393453612924N 108.86132396757603W
Unnamed Road
Rangely
Rio Blanco County
Colorado

Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#4 Looking east.
Ditch drains the main
water plant surface water
and diverted it all through
gates, ultimately to pit
facility 102564.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#5 looking into ditch
in the area approximately
where this spill entered
ditch.

Dec 5, 2024 1:03:08 PM
40.10032258462161N 108.86092859320343W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Main Water Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#6 Looking east.
Ditch drains the main water plant surface water and diverted it all through gates, ultimately to pit facility 102564.

Dec 5, 2024 1:03:33 PM
40.10029840283096N 108.8607834186405W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Dec 5, 2024 1:04:14 PM
40.10034035425633N 108.86070244945586W
Unnamed Road
Rangely
Rio Blanco County
Colorado

Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#7 adjacent to main
water plant facility. These
drainages function as
tertiary containment of
spills at the water plant.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#8 adjacent to main
water plant facility. These
drainages function as
tertiary containment of
spills at the water plant.

Dec 5, 2024 1:06:55 PM
40.09978886693716N 108.8597868103534W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#9 adjacent to main
water plant facility. These
drainages function as
tertiary containment of
spills at the water plant.

Dec 5, 2024 1:07:37 PM
40.09960647672415N 108.85947483591735W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Dec 5, 2024 1:09:32 PM
40.099124517291784N 108.85903243906796W
70695 Colorado 139
Rangely
Rio Blanco County
Colorado

Inspection Photos
Location Name: Main Water Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#10 adjacent to main water plant facility. These drainages function as tertiary containment of spills at the water plant.

Note: pit and pit netting at right rear of photo.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#11

Pit facility 102564

Dec 5, 2024 1:10:03 PM
40.09899669326842N 108.85897787287831W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Main Water
Plant
Location ID:426403
Spill 488568
Inspection Date: 11/21/2024

Photo#12 photo looking
mostly west from the pit
#102564.

Dec 5, 2024 1:16:32 PM
40.09945882949978N 108.8590507954359W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources