

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0519 Entrance to location




Photo # 0522 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0528 Location



Photo # 0531 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0533 Location




Photo # 0559 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Dec 10, 2024 at 12:29:49 PM
+39.234035,-108.257197 ±3.38m
De Beque



Dec 10, 2024 at 12:34:21 PM
+39.233539,-108.256801 ±3.67m
De Beque

Photo # 0560 NW corner of location

Photo # 0565 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0566 SW corner of location



Photo # 0537 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0540 Wildlife hazard



Photo # 0541 Wildlife hazard



Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0546 Wildlife hazard



Photo # 0547 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0549 Wildlife hazard



Photo # 0558 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-31 Pad

Location ID: 312486

Date: 12/10/2024



Photo # 0518 Sign is becoming illegible



Photo # 0525 Sign is becoming illegible