

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Dec 10, 2024 at 1:13:29 PM
+39.226364,-108.209310 ±5.97m
De Beque

Photo # 0574 Entrance to location



Dec 10, 2024 at 1:21:22 PM
+39.225910,-108.209479 ±4.15m
De Beque

Photo # 0587 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Photo # 0575 Location



Photo # 0580 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Photo # 0623 SE corner of location



Photo # 0624 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Photo # 0625 NW corner of location



Photo # 0626 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Photo # 0590 Wildlife hazard




Photo # 0596 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Photo # 0601 Wildlife hazard



Photo # 0605 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 12/10/2024



Photo # 0576 Wellhead sign is weathered & cracked and becoming illegible

