

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 12/10/2024



Photo # 0667 Entrance to location



Photo # 0678 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 12/10/2024



Photo # 0669 Location



Photo # 0673 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 12/10/2024



Photo # 0677 Location



Photo # 0687 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 12/10/2024



Photo # 0695 NE corner of location



Photo # 0697 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 12/10/2024



Photo # 0703 NW corner of location



Photo # 0704 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-27 Pad

Location ID: 312632

Date: 12/10/2024




Photo # 0681 Wildlife hazard



Photo # 0692 Wildlife hazard