

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0710 Entrance to location

Photo # 0736 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0711 Location



Photo # 0717 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0728 Location



Photo # 0735 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0754 NE corner of location



Photo # 0759 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0761 NW corner of location



Photo # 0762 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0725 Wildlife hazard




Photo # 0733 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Dec 10, 2024 at 3:31:24 PM
+39.248533,-108.210927 ±6.24m



Dec 10, 2024 at 3:32:11 PM
+39.248533,-108.210927 ±6.24m

Photo # 0739 Wildlife hazard

Photo # 0740 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0743 Wildlife hazard




Photo # 0745 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0751 Hole in containment liner



Photo # 0753 Hole in containment liner

Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-27 Pad

Location ID: 312624

Date: 12/10/2024



Photo # 0737 Inaccurate tank capacity

