

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2024

Submitted Date:

12/16/2024

Document Number:

711901464

FIELD INSPECTION FORM

Loc ID: 313752 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10657
Name of Operator: PCR OPERATING LLC
Address: 9211 BROADWAY ST #17493
City: SAN ANTONIO State: TX Zip: 78217

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		sperson@passcreekresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
225051	WELL	SI	01/01/2023	OW	087-05445	GEYER, HARRY A-5	SI

General Comment:

FOLLOW-UP FIR – CONDITIONS AT LOCATION REMAIN NON-COMPLIANT – SURFACE MAINTANENCE SHOWS NO INDICATION OF OPERATOR INVOLVEMENT– ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD – LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS – FACILITY BUILDINGS ARE IN DISREPAIR – WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED – FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED. NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES.

Inspected Facilities

Facility ID: 225051 Type: WELL API Number: 087-05445 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>FOLLOW-UP FIR – CONDITIONS AT LOCATION REMAIN NON-COMPLIANT – SURFACE MAINTANENCE SHOWS NO INDICATION OF OPERATOR INVOLVEMENT – ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD – LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS – FACILITY BUILDINGS ARE IN DISREPAIR – WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED – FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED. NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES.</p>	schureky	12/16/2024