

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439

Inspection Doc: 718100109

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 1: Limited inspection due to snow cover. Photo shows interim slopes of the Location that were observable during the inspection. Unable to find evidence that additional reclamation work has been performed, and BMPs to stabilize the seeded soils implemented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 2: Limited inspection due to snow cover. Photo shows interim slopes of the Location that were observable during the inspection. Unable to find evidence that additional reclamation work has been performed, and BMPs to stabilize the seeded soils implemented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 3: Unused equipment, or equipment not necessary for production stored on the east end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



December 10, 2024

Photo 4: Tracking and stabilization BMP at the working pad surface show signs of disrepair. Maintenance advised to ensure control measures remain in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources