

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

12/16/2024

Document Number:

404030597

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 323420 Initial Form 19 or 27 Document number:
Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION
Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6
County: WELD Field Name: WATTENBERG
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 752922 Facility Name: Hochmiller_84411 Facility Type: Commercial
Location: QtrQtr: NWNE Sec: 32 Twp: 3N Range: 65W Meridian: 6
County Name: WELD Latitude: 40.188001 Longitude: -104.683636

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 123939 Document Name: Size of file in bytes: 18609 File Name: 2024_09_19_Hochmiller 84411-A Isotech SIW
ECMC.xlsx
SampleType: Matrix:
Facility ID: 752922 Sample ID: 663996 Sample Name: Hochmiller 84411--A Sample Date: 09/19/2024
Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 938724

Batch ID: 123940		Document Name: Size of file in bytes: 18471		File Name: 2024_09_19_Hochmiller 84411-A Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 663997	Sample Name: Hochmiller 84411--A		Sample Date: 09/19/2024	
Collection Point: Dom		Matrix: GAS	Pre Post: Voluntary Post drill		
Project Number: _____		Remediation Number: _____	Complaint Number: _____		NOAV Number: _____
Inspection Number: _____		Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 938737	

Batch ID: 123936		Document Name: Size of file in bytes: 31111		File Name: 2024_09_19_Hochmiller 84411--A SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 663993	Sample Name: Hochmiller 84411--A		Sample Date: 09/19/2024	
Collection Point: Dom		Matrix: WATER	Pre Post: Voluntary Post drill		
Project Number: _____		Remediation Number: _____	Complaint Number: _____		NOAV Number: _____
Inspection Number: _____		Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA67436-1	

Batch ID: 123935		Document Name: Size of file in bytes: 19376		File Name: 2024_09_19_Hochmiller 84411-A Trip Blank SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 663992	Sample Name: Hochmiller 84411--A		Sample Date: 09/19/2024	
Collection Point: TB		Matrix: WATER	Pre Post: Voluntary Post drill		
Project Number: _____		Remediation Number: _____	Complaint Number: _____		NOAV Number: _____
Inspection Number: _____		Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA67437-1	

Batch ID: 123940		Document Name: Size of file in bytes: 18471		File Name: 2024_09_19_Hochmiller 84411-A Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 663998	Sample Name: Hochmiller 84411--A		Sample Date: 09/19/2024	
Collection Point: Dom		Matrix: WATER	Pre Post: Voluntary Post drill		
Project Number: _____		Remediation Number: _____	Complaint Number: _____		NOAV Number: _____
Inspection Number: _____		Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 938737	

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
752922	404030614	2024_09_19_Hochmiller 84411--A SGS.pdf	Analytical Laboratory Report	PDF
752922	404030607	2024_09_19_Hochmiller 84411-A Isotech NG4.pdf	Analytical Laboratory Report	PDF
752922	404030625	2024_09_19_Hochmiller_84411_A_Spigot_Wellhead_Loc.jpg	Photographs	JPG
752922	404030612	2024_09_19_Hochmiller 84411-A Isotech SIW.pdf	Analytical Laboratory Report	PDF
752922	404030618	2024_09_19_Hochmiller_84411_A_FS_ECMC.pdf	Field Data Report	PDF
752922	404030627	2024_09_19_Hochmiller_84411_A_Wellhead.jpg	Photographs	JPG
752922	404030621	2024_09_19_Hochmiller_84411_A_PrePostPurge.jpg	Photographs	JPG
752922	404030602	2024_09_19_Hochmiller 84411-A Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
752922	404030622	2024_09_19_Hochmiller_84411_A_Spigot.jpg	Photographs	JPG

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	12/18/2024
Total: 1 comment(s)		