

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024




Photo # 1380 Entrance to location

Photo # 1412 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1382 Location



Photo # 1383 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1387 Location



Photo # 1400 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1401 Location



Photo # 1410 Location

Inspection Photos
Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad
Location ID: 452807
Date: 12/17/2024



Photo # 1430 Location



Photo # 1438 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1446 NW corner of location



Photo # 1447 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1450 SE corner of location



Photo # 1451 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1452 Location



Photo # 1390 Failure to maintain multiple chemical BMP/chemical containments approximately 3/4th full of fluid/not sufficient to contain possible spill

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Dec 17, 2024 at 2:53:12 PM
+39.558201, -108.205164 ±2.82m



Dec 17, 2024 at 2:54:40 PM
+39.558201, -108.205164 ±2.82m

Photo # 1391 Failure to maintain multiple chemical BMP/chemical containments approximately 3/4th full of fluid/not sufficient to contain possible spill

Photo # 1393 Failure to maintain multiple chemical BMP/chemical containments approximately 3/4th full of fluid/not sufficient to contain possible spill

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1405 Wildlife hazard



Photo # 1408 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1409 Wildlife hazard



Photo # 1423 Tank heater PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0697-03-07 Pad

Location ID: 452807

Date: 12/17/2024



Photo # 1441 Wildlife hazard



Photo # 1444 Wildlife hazard