

Final Reclamation and Stormwater Inspection

December 9, 2024

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10113

Location ID: 320019

Well Name: MITCHEM #2-26X

Inspection Document #: 718600074

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MITCHEM #2-26X
Location ID: 320019



Photo 1. Looking south across former tank battery. It appears pipeline infrastructure is midstream gathering equipment.



Photo 2. Photo taken looking southeast on the south side of tank battery. Metal debris, soil pile and wooden posts remain on site. Noxious weeds (Musk thistle) and undesirable vegetation (Koshia) are present throughout the site



Inspection Photos
Location Name: MITCHEM #2-26X
Location ID: 320019



Photo 3. Looking north across tank battery. Tanks and cattle grate have been removed. Equipment and debris remain on site.



Photo 4. Photo taken looking east at access road entrance. Illustrating bare soil.



Inspection Photos
Location Name: MITCHEM #2-26X
Location ID: 320019



Photo 5. Looking south across well site. Electrical equipment remains on location and site has not been reclaimed.



Photo 6. Photo taken looking south from wellsite. Electrical equipment and post on location, bare soil and undesirable weedy vegetation.