

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/19/2024

Document Number:

710100322

FIELD INSPECTION FORM

Loc ID 408839 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 80530

Name of Operator: SNYDER OIL CORP

Address: 333 WEST SHERIDAN AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Chamard, Megan		megan.chamard@state.co.us	
J, CYNTHIA	405 288 8856	cindy.chiba@dvn.com	Designated Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249289	WELL	PA	07/08/1993	DA	123-17091	CAMP 30-14J	PA

General Comment:

ECMC Environmental Inspection of Snyder Oil's (Operator) CAMP 30-14J well (Loc 408839/API 123-17091).

On November 29, 2023, Kerr-McGee Oil & Gas Onshore LP (KMOG) performed a re-entry on the Camp 30-14J wellhead. Post re-entry, KMOG performed cut & cap procedures and the soil within the cut & cap excavation was screened and sampled. Laboratory results indicate soil impacts in exceedance of Table 915-1 standards are present in the excavation. KMOG notified ECMC of the historic release on November 12, 2024, and provided a decommissioning package containing sampling maps, results tables, field notes, GPS data and the associated lab report. The decommissioning package has been attached to this Field Inspection Report.

The CAMP 30-14J wellhead is classified as dry and abandoned and was plugged and abandoned on 7/8/1993 under Snyder Oil Corp.

During the inspection ECMC observed an open excavation surrounded by cattle fencing. Contract personnel were on location at the time of this field inspection. Crews indicated the cattle fencing would be removed and the excavation backfilled with the soil stockpiled on location. Soil stockpiled on location is from the excavation. Photos attached to document site conditions at the time of inspection.

Inspected Facilities									
Facility ID:	249289	Type:	WELL	API Number:	123-17091	Status:	PA	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spills/Releases:

Type of Spill:

Estimated Spill Volume:

Comment:

A third party Operator identified a historic release during offset well re-entry of the previously plugged and abandoned CAMP 30-14J well owned by Snyder Oil Corp.

Corrective Action:

Pursuant to Rule 912.b.(3), If the Operator did not submit the 24 Hour Notification through a Form 19 – Initial, the Operator will submit a Form 19 – Initial no less than 72 hours after discovery of the Spill or Release unless the Director extends the timeframe in writing.Operator shall submit an Initial Form 19 Spill/ReleaseReport by EOB December 23, 2024.

Date:

12/23/2024

Reportable:

YES

GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num: Owner Name: GPS :

Lat Long

Field Parameters:

Sample Location: Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100323	Camp 30-14J Decommissioning Package	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834548
710100324	Camp 30-14J Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834549

Date Run: 12/19/2024 Doc [#710100322]

Page 3 of 3