

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Energy and Carbon Management Commission
40.78601, -103.98552, 5043.7ft
12/18/2024 12:25:23



Energy and Carbon Management Commission
40.78588, -103.98553, 5036.5ft
12/18/2024 12:25:48

Photo 1 – Wellhead

Photo 2 – Pumping Unit

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Photo 3 – Well Sign



Photo 4 – ECD

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Photo 5 – Heater Treater



Photo 6 – Tank Battery

Inspection Photos
Location Name: Wildhorse 04-0424H
Location ID: 427197



Photo 7 – Tank Battery Sign



Photo 8 – Tank Battery