

# Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-16 Pad

Location ID: 312629

Date: 12/11/2024



Photo # 0968 Entrance to location

Photo # 0974 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-16 Pad

Location ID: 312629

Date: 12/11/2024



Photo # 0969 Location



Photo # 0970 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-16 Pad

Location ID: 312629

Date: 12/11/2024




Photo # 0979 Location



Photo # 0985 NE corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-16 Pad

Location ID: 312629

Date: 12/11/2024



Photo # 0986 SE corner of location



Photo # 0987 SW corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-16 Pad

Location ID: 312629

Date: 12/11/2024



Photo # 0988 NW corner of location



Photo # 0983 Wildlife hazard

# Inspection Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/3-16 Pad

Location ID: 312629

Date: 12/11/2024




Photo # 0975 Label is peeling

Photo # 0976 Label is peeling