

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1003 Entrance to location




Photo # 1019 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1004 Location



Photo # 1010 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1015 Location



Photo # 1018 Location



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1034 Location



Photo # 1043 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1038 SW corner of location



Photo # 1039 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1040 SE corner of location



Photo # 1042 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1024 Label is showing signs of disrepair and becoming illegible




Photo # 1023 Label is showing signs of disrepair

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024




Photo # 1021 Label is starting to peel



Photo # 1026 Label is showing signs of disrepair



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DIXON A PAD

Location ID: 335550

Date: 12/16/2024



Photo # 1028 Debris



Photo # 1031 Debris