

Final Reclamation and Stormwater Inspection

December 9, 2024

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10113

Location ID: 320078

Well Name: MITCHEM #34-26

Inspection Document #: 718600076

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MITCHEM #34-26
Location ID: 320078



Photo 1. Photo Looking southeast towards wellsite along access road. Red arrow points at well pad which has not been recontoured.



Photo 2. Photo taken looking southeast across wellsite. Undesirable weedy vegetation is present and poor vegetation coverage.



Inspection Photos
Location Name: MITCHEM #34-26
Location ID: 320078



Photo 3. Looking west from wellsite. Noxious weeds (Musk thistle, Mullein) are present on location.



Photo 4. Photo taken looking north across wellsite. See Photo 2 comments.

Inspection Photos
Location Name: MITCHEM #34-26
Location ID: 320078



Photo 5. Looking northeast from wellsite. Electric Utilities remain on site.



Photo 6. Aerial photograph from 09/1972. Illustrating existing access road.