

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1048 Entrance to location




Photo # 1062 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1049 Location



Photo # 1050 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1056 Location



Photo # 1061 Location



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1081 Location



Photo # 1078 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1079 SW corner of location



Photo # 1080 SE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1083 NE corner of location



Photo # 1060 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1071 Debris



Photo # 1072 Debris

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1073 Debris



Photo # 1077 Debris

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC DEVER C PAD

Location ID: 335551

Date: 12/16/2024



Photo # 1075 Staining

