

# Inspection Photos

12/18/2024

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 334426

**Inspection Doc:** 718100122

Mesa County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



**Photo 1:** Photos 1-2 taken from the slopes on the north end of the Location. Photos show BMPs to stabilize, as well as to minimize erosion and degradation at the bare slopes remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources