

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1094 Entrance to location




Photo # 1138 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1097 Location



Photo # 1098 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1109 Location



Photo # 1115 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1137 Location



Photo # 1159 Location



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1160 SE corner of location



Photo # 1161 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1162 NW corner of location



Photo # 1163 SW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1128 Wildlife hazard




Photo # 1134 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1154 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 1156 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1121 Debris



Photo # 1122 Debris

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1135 Debris



Photo # 1149 Staining

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024



Photo # 1150 Staining




Photo # 1114 Sign becoming illegible

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC Gentry B Pad

Location ID: 335549

Date: 12/16/2024




Photo # 1111 Sign becoming illegible




Photo # 1112 Sign becoming illegible