

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28NENE

Location ID: 335080

Date: 12/19/2024



Location Entrance – Photo #05491



Location – Photo #05492

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28NENE

Location ID: 335080

Date: 12/19/2024



Location – Photo #05495



Location – Photo #05494

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28NENE

Location ID: 335080

Date: 12/19/2024



Location – Photo #05498



Location – Photo #05497

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/28NENE

Location ID: 335080

Date: 12/19/2024



Weathered and Illegible Wellhead Sign – Photo #05493